


INSTRUCTION MANUAL

TABLE LANTERN HASTINGS



Use

Built-in Li-on battery 3.7V 4000 mAh

Including charging cable

Charging port USB Type C

Charging indicator:

- charging: red
- full: green

Charging time: 6 hours

Burntime: 4-20 hours

Press 1 time: ON

Press and hold for an extended duration to activate the full dimming switch.

